

Internal Photos




Photo 1 – Top Metal Plate Removed




Photo 2 – Plastic & PCB Moved




Photo 3 – PCB Top View




Photo 4 – Closeup of LoRa Crystal and Radio

Bluetooth
Module
(U6)

Bluetooth
Antenna
(J1)




Photo 5 – Closeup of Bluetooth module, including Antenna




Photo 6 – Bluetooth Module, shield removed