


Report No.: EED32N00018401 Page 29 of 39

PHOTOGRAPHS OF TEST SETUP

Test model No.:DBP-8278B



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)

Hotline: 400-6788-333 www.cti-cert.com E-mail: info@cti-cert.com Complaint call: 0755-33681700 Complaint E-mail: complaint@cti-cert.com