











Report No. : EED32Q81688501









Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.











Page 34 of 71

## 9 PHOTOGRAPHS OF EUT Constructional Details



## View of Product-01





Report No. : EED32Q81688501









View of Product-03



View of Product-04









