

**Test Report S/N:** 45461921 R1.0 **Project:** 1658

## **EXHIBIT 14 - PHOTOS - DUT INTERNAL**

Figure E14.1 – Internal – DUT Split






Figure E14.2 – Internal – DUT Split, Main PCB Removed





Figure E14.3 - Internal - DUT Split, Main PCB






Figure E14.4 - Internal - DUT Split, Main PCB, Shield Removed






Figure E14.5 – Internal – DUT Split, Main PCB, Back Side

