

#### 1. INTERNAL PHOTOGRAPHS

### 1.1 Disassembled sliding part






## 1.2 Phone after disassembling PWB and A-Cover





### 1.3 Disassembled Phone





## 1.4 D-Cover with GSM-Antenna, BT-Antenna and Speaker







# 1.5 Core PWB (without shieldings)



