


Report No. : EED32O80416501 Page 29 of 33

## 9 PHOTOGRAPHS OF TEST SETUP

Test model No.: CMMC01



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Page 30 of 33 Report No.: EED32O80416501



