



APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission

Front



Rear (below 1 GHz)



Rear (above 1 GHz)



Pre-check of Worst Case Position

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report