


Report No.: EED32Q81896401 Page 39 of 46

7 PHOTOGRAPHS OF TEST SETUP



AC conducted emissions



Radiated spurious emission Test Setup-1(Below 1GHz)















Report No.: EED32Q81896401





Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz)













Report No.: EED32Q81896401

















