1.0 INTERNAL PHOTOS



Figure 1 – Top View

Test Report S/N: 1402080-R1.0 Test Report Issue Date: 10 February 2016



Figure 2 – Bottom View M-1






Figure 3 – Front Assembly




Figure 4 – Front Assembly Breakout





Figure 5 – Main Assembly Top View






Figure 6 – Main Assembly Bottom View





Figure 7 – Tx-Rx Section

10 February 2016





Figure 8 – AM Modulator and Regulator (1)





Figure 9 – AM Modulator and Regulator (2)