





## 9 PHOTOGRAPHS OF TEST SETUP

Test model No.: DBP-62A1B




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O81898101 Page 38 of 48



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**Conducted Emissions Test Setup** 









