


APPENDIX 3: Photographs of test setup

Conducted Emission




Radiated Spurious Emission


Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)




Worst Case Position

Module


X-axis



Y-axis




Z-axis




Antenna 1 (J2)


X-axis



Y-axis




Z-axis




Antenna 2 (J3)


X-axis



Y-axis



Z-axis



End of Report