


Report No. : EED32N81058701 Page 40 of 52

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: LeRes-S1




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32N81058701 Page 41 of 52



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup









