























A3.7 LTE Band 7










A3.8 LTE Band 25











A3.9 LTE Band 30







A3.10 LTE Band 41










A3.11 LTE Band 66













A3.12 NR n2











A3.13 NR n66













A4. Transmitter unwanted emissions (spurious) Test Result

A4.1 LTE 2UL 5B



