





PHOTOGRAPHS OF TEST SETUP

Test model No.: RM110



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32N80491502 Page 54 of 55



Radiated spurious emission Test Setup-3(Above 1GHz)



Conducted emission Test Setup













Report No. : EED32N80491502 Page 55 of 55

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32N80491501 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

