


Report No.: EED32N80049701 Page 30 of 45

PHOTOGRAPHS OF TEST SETUP

Test model No.: QTZ-40-T-01



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)














Report No. : EED32N80049701 Page 31 of 45



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There are absorbing materials under the ground.













Report No.: EED32N80049701







Conducted Emissions Test Setup











