







9 PHOTOGRAPHS OF TEST SETUP

Test model No.: RM110



Radiated spurious emission Test Setup-1(Below 1GHz)







Report No. : EED32N80457601







Conducted emission Test Setup



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.