

Document ID	https://docs.google.com/document/d/1gna4pfNLXpfrusYs13jO6xFqjGkb5N49/
Responsible	Oystein Moldsvor
Classification	Confidential

Revision History Table		
Named revision	Date	Comment:
01	2024-01-04	First version

External Photos



Figure 1: Picture of the front side of 102737 - Door and Window Sensor US



Figure 2: Picture of the back side of 102737 - Door and Window Sensor US with the mounting bracket removed.



Figure 3: Picture of the back side of 102737 - Door and Window Sensor US with the mounting bracket installed.