


Report No. :EED32O80866101 Page 37 of 51

## 9 PHOTOGRAPHS OF TEST SETUP

Test model No.: DBP-6293B




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O80866101





Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**CONDUCTED EMISSION TEST SETUP** 









