Tested Model: MPD8920

Photo of Power Line Conducted Emission Measurement





Test Photos Page 1 of 4

Radiated Spurious Emissions Test View (Below 1GHz)



Radiated Spurious Emissions Test View (Above 1GHz)



Test Photos Page 2 of 4

Multiple Model: MPD8919


Photo of Power Line Conducted Emission Measurement





Test Photos Page 3 of 4

Radiated Spurious Emissions Test View (Below 1GHz)



Test Photos Page 4 of 4