



Model 1807 Internal Photographs

Display Side







Display Back




Display Removed




CPU shield can and heat pipe removed




Shield Cans Removed



Antenna Deck Removed



Motherboard Component Side



Motherboard Bottom

