


Report No. :EED32O80591201



Page 22 of 34

PHOTOGRAPHS OF TEST SETUP

Test model No.:LEB50E



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No. :EED32O80591201





Page 23 of 34



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emission Test Setup









