

Test Plots(Note: The 7dB is the Insertion loss of the RF cable, Power Splitter and DC Block, which was offset into the Spectrum Analyzer):




Page 136 of 250

Report No.: CR230851060-00




Report No.: CR230851060-00




Page 138 of 250

Report No.: CR230851060-00




Report No.: CR230851060-00



Page 140 of 250

Report No.: CR230851060-00



Page 141 of 250