

4. Internal Photograph of the Host

Host 1









Bluetooth and WLAN Antenna





Host 2





Report No.: EP0D1804







Bluetooth and WLAN Antenna



————THE END————