



APPENDIX 3: Photographs of test setup

Conducted Emission




Radiated Spurious Emission

Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)




Worst Case Position


Module
X-axis



Y-axis



Z-axis



Antenna: ANT G


X-axis



Y-axis




Z-axis




Antenna: ANT R

X-axis



Y-axis



Z-axis



End of Report