




PHOTOGRAPHS OF TEST SETUP

For Internal antenna:



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Page 39 of 56 Report No.: EED32P80329501



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emissions Test Setup-4(Above 1GHz)











Report No.: EED32P80329501 Page 40 of 56

For External antenna:



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32P80329501 Page 41 of 56



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emissions Test Setup-4(Above 1GHz)









