



Report No. : EED32P81306401









Report No. : EED32P81306401



Page 33 of 43



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup











