DEKRA Certification, Inc. 405 Glenn Dr. Suite 12, Sterling, VA 20164 United States of America



## Appendix B: Photographs

## DEKRA Certification, Inc. 405 Glenn Dr. Suite 12, Sterling, VA 20164 United States of America





Figure B1. DUT Front view




Figure B2. DUT with Accessories

## DEKRA Certification, Inc. 405 Glenn Dr. Suite 12, Sterling, VA 20164 United States of America





Figure B3. Conducted test setup



Figure B4. Conducted test setup






Figure B5. Radiated emission Test Setup Low Range




Figure B6. Radiated emission Test Setup Low Range - Back side






Figure B7. Radiated emission Test setup High Range




Figure B8. Radiated emission Test Setup High Range - Back side






Figure B9. Radiated emission Test Setup High Range (>18GHz)






Figure B10. Conducted sample internal top view




Figure B11. Conducted sample internal rear view






Figure B12. Radiated sample internal top view




Figure B13. Radiated sample internal rear view