


Report No.: EED32O81356301 Page 29 of 53

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: KL3684320



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Page 30 of 53 Report No.: EED32O81356301



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.

