




Report No. : EED32Q80116701











Radiated spurious emission Test Setup-2(Below 1GHz)(close up)





Report No. : EED32Q80116701



Page 34 of 42



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.





