



APPENDIX F

FREQUENCY STABILITY MEASUREMENTS Environmental

CONTENTS:
FREQUENCY vs. TEMP.

INFORMATION

* CLIENT: **HYUNDAI ELECTRONICS AMERICA**
3103 NORTH FIRST STREET, SAN JOSE, CALIFORNIA, 95134
* CONTACT: **DR SANG KYOON HYUN** 408/894-0437
* PRODUCT: **PICO_BTS, DIGITAL COMMUNICATION SYSTEM**
* REPORT FILE: 2K010401
* FILE NAME: APPENDIX F
* DATE: 02/16/00
* SUBMITTED BY: ELECTRONIC COMPLIANCE LABORATORIES, INC.
1249 BIRCHWOOD DRIVE, SUNNYVALE, CALIFORNIA 94089

* CONTACT: **CHIP MATHENY** 408/747-1490 CHIP@ECLABS.COM





Frequency Measurements

02/10/00

		Temp. Vs. Frequency Stability	
--	--	-------------------------------	--

Value	Temp. in C	Channel 356	Channel 500	Channel 644
	Room	880.680001	885.000001	889.320001
Negative	30	880.680001	885.000001	889.320001
Negative	20	880.680001	885.000001	889.320001
Negative	10	880.680001	885.000002	889.320002
	0	880.680001	885.000001	889.320001
Positive	10	880.680001	885.000000	889.320000
Positive	20	880.680001	885.000002	889.320001
Positive	30	880.680002	885.000001	889.320002
Positive	40	880.680002	885.000002	889.320002
Positive	50	880.680001	885.000001	889.320001