

Page 46 of 58 Report No.: EED32P81875001

7 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Below 1GHz) close up














Report No.: EED32P81875001







Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.









