


Report No.: EED32Q80761701 Page 38 of 47

9 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1 (Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32Q80761701 Page 39 of 47



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

