


Annex B Test Setup Photos

Antenna Location





REPORT No. : SZ21010296S01


Head




Right Cheek



Right Tilt




Left Cheek




Left Tilt

Body




Front Side (Test distance: 10mm)




Back Side (Test distance: 10mm)




Left Side (Test distance: 10mm)



Right Side (Test distance: 10mm)



Top Side (Test distance: 10mm)



Bottom Side (Test distance: 10mm)