

Report No.: EED32O81521002

Page 49 of 51

7 PHOTOGRAPHS OF TEST SETUP

Test Model No.: S1621HB



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32O81521002





Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emission













Report No.: EED32O81521002



8 PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32O81521001 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

