#### 1. INTERNAL PHOTOGRAPHS

#### 1.1 Disassembled sliding part



Internal photographs Exhibit 9 Applicant: Nokia Corporation



1.2 Phone after disassembling PWB and A-Cover

Internal photographs Exhibit 9 Applicant: Nokia Corporation

#### **1.3 Disassembled Phone**



Internal photographs Exhibit 9 Applicant: Nokia Corporation



1.4 D-Cover with GSM-Antenna, BT-Antenna and Speaker

Internal photographs Exhibit 9 Applicant: Nokia Corporation

1.5 Core PWB (without shieldings)



Internal photographs Exhibit 9 Applicant: Nokia Corporation