




Page 36 of 58

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: CX40



Radiated spurious emission Test Setup-1(Below 1GHz)















Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup














 (\mathcal{A})







Page 38 of 58



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

