


Report No. : EED32P80065901 Page 29 of 35

9 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)




Radiated spurious emission Test Setup-2(Below 1GHz)close up photo



Report No.: EED32P80065901 Page 30 of 35



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)close up photo













Page 31 of 35 Report No.: EED32P80065901



