


## **RF Test Setup Photo**

Description: Radiated Spurious Emissions Test Setup (above 1GHz)



Description: Conducted Test Setup





## **SAR Test Setup Photo**

Description: Extremity Front Position with 0mm gap



Description: Body Back Position with 0mm gap





Description: Extremity Left Position with 0mm gap



Description: Extremity Right Position with 0mm gap



Report No.: 2203RSU031-UT



Description: Extremity Top Position with 0mm gap



Description: Extremity Bottom Position with 0mm gap

