

Test Result : Pass (Appendix B)

Radiated Test Placement: (Photographs)





## Conducted Test Placement: (Photographs)



P/S: Because the space is not large enough for taking photograph of rear side. Please refer to the radiated testing set up.