

Test Report S/N: 45461911-R1.0 **Project:** 1657

EXHIBIT 17 - PHOTOS - DUT INTERNAL

Figure E17.1 - Internal, Front Cover Removed





Figure E17.2 - Internal, Front Cover Removed





Figure E17.3 - Internal, Battery Removed





Figure E17.4 - Internal, Back Cover Removed





Figure E17.5 - Internal, Main PCB, Top





Test Report S/N: 45461911-R1.0 **Project:** 1657

2AEOCPC219

Figure E17.6 - Internal, Main PCB, Button Side





Figure E17.7 - Internal, Audio PCB, Bottom






Figure E17.8 - Internal, Audio PCB, Top

