

ANNEX B

PHOTOGRAPHS

(Number of photographs: 6)

Report No.: 20234RET.101

Report No.: 20234RET.101	Page: 1 of 7
Date: 2004-09-09	Annex B




1. Equipment (external view)



Report No.: 20234RET.101	Page: 2 of 7
Date: 2004-09-09	Annex B



2. Equipment for conducted measurements.



Report No.: 20234RET.101	Page: 3 of 7
Date: 2004-09-09	Annex B




3. General test set-up for radiated measurements.



Report No.: 20234RET.101	Page: 4 of 7
Date: 2004-09-09	Annex B




4. Test set-up for radiated measurements below 1 GHz.



Report No.: 20234RET.101	Page: 5 of 7
Date: 2004-09-09	Annex B




5. Test set-up for radiated measurements above 1 GHz.



Report No.: 20234RET.101	Page: 6 of 7
Date: 2004-09-09	Annex B



6. Test set-up for RF conducted measurements.



Report No.: 20234RET.101	Page: 7 of 7
Date: 2004-09-09	Annex B