



APPENDIX 3: Photographs of test setup

Conducted Emission

S/N: 10




S/N: 11




Radiated Spurious Emission


S/N: 10
Front




S/N: 11
Front




Rear (below 1 GHz)




Rear (below 1 GHz)



Rear (above 1 GHz)




Rear (above 1 GHz)




Worst Case Position


S/N: 10
X-axis




S/N: 11
X-axis




Y-axis




Y-axis



Z-axis



Z-axis



End of Report