Report No.: AGC07716190801FE03 Page 61 of 77

CONDUCTED EMISSION TEST SETUP



Report No.: AGC07716190801FE03 Page 62 of 77

APPENDIX B: PHOTOGRAPHS OF EUT

ALL VIEW OF EUT



Report No.: AGC07716190801FE03

Page 63 of 77

TOP VIEW OF EUT



BOTTOM VIEW OF EUT



Page 64 of 77





BACK VIEW OF EUT



Page 65 of 77

LEFT VIEW OF EUT




RIGHT VIEW OF EUT




Page 66 of 77

OPEN VIEW - OF EUT-1




OPEN VIEW - OF EUT-2




Page 67 of 77

OPEN VIEW - OF EUT-3



OPEN VIEW - OF EUT-4




OPEN VIEW - OF EUT-5




VIEW OF BATTERY




INTERNAL VIEW-1 OF EUT




INTERNAL VIEW-2 OF EUT



INTERNAL VIEW-3 OF EUT




INTERNAL VIEW-4 OF EUT




INTERNAL VIEW-5 OF EUT




INTERNAL VIEW-6 OF EUT




INTERNAL VIEW-7 OF EUT




INTERNAL VIEW-8 OF EUT




INTERNAL VIEW-9 OF EUT




INTERNAL VIEW-10 OF EUT




INTERNAL VIEW-11 OF EUT




INTERNAL VIEW-12 OF EUT




INTERNAL VIEW-13 OF EUT




INTERNAL VIEW-14 OF EUT




INTERNAL VIEW-15 OF EUT



INTERNAL VIEW-16 OF EUT



INTERNAL VIEW-17 OF EUT



----END OF REPORT----