INTERNAL BUOTO OF A BUO	
INTERNAL PHOTOGRAPHS	
This document contains 4 photographs	
This document contains 1 photographs	


Photograph No.1 PMD2P PIR detector internal view



Photograph No.2 PMD2P PIR detector main PCB front view







Photograph No.4 Antenna close view

