


Report No.: EED32L00247001








PHOTOGRAPHS OF TEST SETUP

Test mode No:AG-60A



Radiated spurious emission Test Setup-1 (Below 30M)



Radiated spurious emission Test Setup-2 (Below 1GHz)



Hotline: 400-6788-333

www.cti-cert.com E-mail: info@cti-cert.com Complaint call: 0755-33681700 Complaint E-mail: complaint@cti-cert.com



Report No.: EED32L00247001







Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.













Report No.: EED32L00247001





Page 82 of 88

























































