

Test report No.	FCC_IC_SL17060501-ZBR-021-BLE_Rev2.0
Page	11 of 38

## 6.6 EUT Test Setup Photos




Radiated Emissions (>1GHz) – Front View (EUT vertical)

Radiated Emissions (>1GHz) - Rear View (EUT vertical)

775 Montague Expressway, Milpitas, CA 95035, USA • Phone: (+1) 408 526 1188 • Facsimile (+1) 408 526 1088

L

Visit us at: www.siemic.com; Follow us at:



Radiated Emissions (>1GHz) – Front View (EUT horizontal)

Radiated Emissions (>1GHz) – Rear View(EUT horizontal)

Ŧ

In

U

775 Montague Expressway, Milpitas, CA 95035, USA • Phone: (+1) 408 526 1188 • Facsimile (+1) 408 526 1088

Visit us at: www.siemic.com; Follow us at: