




B7_5M_QPSK_25@0_CH_20775




B7_5M_16QAM_1@0_CH_20775




B7_5M_16QAM_25@0_CH_20775




B7_5M_QPSK_1@24_CH_21425




B7_5M_QPSK_25@0_CH_21425



B7_5M_16QAM_1@24_CH_21425



B7_5M_16QAM_25@0_CH_21425



N/A

APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

*** End of Report ***

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.
