



Photo #7.
Radio unit with Unidirectional antenna UNI-28-4 P/N 858109
Spurious emission test




Photo #8.
Radio unit with Unidirectional antenna UNI-28-4 P/N 858109
Spurious emission test




Photo #9

**Radio unit with Unidirectional antenna UNI-28-5.8 P/N 872811
Spurious emission test**



Photo #10
Radio unit with Unidirectional antenna UNI-28-5.8 P/N 872811
Spurious emission test



Photo #11
Radio unit with MAXRAD Omni antenna model MFB58008
Spurious emission test