

PHOTOGRAPHS OF THE TESTSETUP OF A

BRAND Vecos, MODEL V3+

report written by: R. van der Meer June 08, 2021

TÜV Rheinland Nederland B.V.

Eiberkamp 10
9351VT Leek
The Netherlands

Telephone: +31 888887888
Internet: www.tuv.com/nl
E-mail: products@nl.tuv.com

Table of contents

1	PHOTOGRAPHS OF THE TEST SETUP.	3
1.1	RADIATED EMISSIONS.....	3
1.1.1	<i>Radiated emissions setup.</i>	3
1.2	PHOTOGRAPHS OF THE CARRIER STABILITY SETUP.....	6
2	PHOTOGRAPH TEST SETUP, AC POWER LINE CONDUCTED EMISSIONS.....	7

1 Photographs of the test setup.

1.1 Radiated emissions.

1.1.1 Radiated emissions setup.




Photo 1 Photograph test setup radiated emissions 30-1000 MHz, report section 3.1




Photo 2 Photograph test setup radiated emissions <30 MHz-planar, report section 3.1




Photo 3 Photograph test setup radiated emissions <30 MHz- Axial, report section 3.1




Photo 4 Photograph test setup radiated emissions <30 MHz- Z, report section 3.1




Photo 5 Photograph test setup radiated emissions-table top setup , report section 3.1




Photo a/b/c EUT positions X,Y and Z

1.2 Photographs of the carrier stability setup



Photo 6 Photograph test setup Carrier stability




Photo 7 Photograph test setup Carrier stability

2 Photograph test setup, AC Power Line Conducted emissions



Photo 8a/b: Photographs AC Power Line conducted emissions 0.15-30 MHz, report section 4.2





TÜVRheinland®
Precisely Right.

< END of Document >