

Report No.: EED32N80338501

## 7 PHOTOGRAPHS OF TEST SETUP





Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)















Report No.: EED32N80338501







Radiated spurious emission Test Setup-5(Above 1GHz)
There are absorbing materials under the ground.



**AC Power Line Conducted Emission** 

















